



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

January 29, 2024

Loss of Power Steering Assist

Loss of power steering assist while driving increases the risk of a crash.

NHTSA Campaign Number: 24V022000

Manufacturer Mazda North American Operations

Components STEERING

Potential Number of Units Affected 43,752

Summary

Mazda North America Operations (Mazda) is recalling certain 2024 CX-90 vehicles. An assembly issue with the worm gear in the steering system may result in a sudden loss of power steering assist.

Remedy

Dealers will replace the spring engaging the worm gear and reapply grease to the gear teeth, free of charge. Owner notification letters are expected to be mailed March 18, 2024. Owners may contact Mazda customer service at 1-800-222-5500 Option 6. Mazda's number for this recall is 6524A.

Vehicle

MAKE	MODEL	YEAR
MAZDA	CX-90	2024

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera image that does not display while in reverse decreases the driver's visibility, increasing the risk of injury or crash.

NHTSA Campaign Number: 24V023000

Manufacturer Jaguar Land Rover North America, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 58,729

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018-2022 Range Rover and Range Rover Sport vehicles equipped with a Surround Camera System. Water may enter into the rearview camera, which can cause the rearview camera image not to appear on the display or display a distorted image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will inspect the rearview camera and add a new seal or replace the camera, free of charge. Owner notification letters are expected to be mailed March 8, 2024. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N778.

Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2018-2022
LAND ROVER	RANGE ROVER SPORT	2018-2022

Blind Spot Monitoring System May Fail

Without a functioning blind spot monitoring system, the driver may be unaware of a vehicle in their blind spot, which can increase the risk of a crash.

NHTSA Campaign Number: 24V024000

Manufacturer Winnebago Industries, Inc.

Components LANE DEPARTURE

Potential Number of Units Affected 844

Summary

Winnebago Industries, Inc. (Winnebago) is recalling certain 2021-2023 Ekko motorhomes. The blind spot monitoring system may fail without warning to the driver.

Remedy

Dealers will install a new blind spot monitoring system, free of charge. Owner notification letters are expected to be mailed February 16, 2024. Owners may contact Winnebago customer service at 1-641-585-6939 or 1-800-537-1885.

Vehicle

MAKE	MODEL	YEAR
WINNEBAGO	EKKO	2021-2023

Electric Motor Cable May Have Insufficient Ground

An insufficient electrical ground can increase the risk of electric shock during service work, and also increase the risk of a fire.

NHTSA Campaign Number: 24V039000

Manufacturer BMW of North America, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 107

Summary

BMW of North America, LLC (BMW) is recalling certain 2024 Rolls Royce Spectre electric vehicles. The ground connection cable between the front electric motor and the vehicle chassis may contain adhesive residue which can increase electrical resistance and cause an insufficient ground.

Remedy

Dealers will inspect the ground cable connection and remove any residue as necessary, free of charge. Owner notification letters are expected to be mailed March 15, 2024. Owners may contact Rolls Royce customer service at 1-877-877-3735.

Vehicle

MAKE	MODEL	YEAR
ROLLS-ROYCE	SPECTRE	2024
