



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

April 1, 2024

### Air Bag May Not Deploy

An air bag that does not deploy during a crash can increase the risk of injury.

**NHTSA Campaign Number:** 24V227000

**Manufacturer** Subaru of America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 118,723

#### Summary

Subaru of America, Inc. (Subaru) is recalling certain 2020-2022 Outback and Legacy vehicles. A capacitor in the sensors for the Occupant Detection System (ODS) may crack and short circuit, which can prevent the front passenger air bag from deploying in a crash.

#### Remedy

Dealers will replace the ODS sensors on the front passenger seat, free of charge. Interim letters informing owners of the safety risk are expected to be mailed May 21, 2024. Owners will receive a second letter once the remedy is available. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WRA-24.

#### Vehicles

---

MAKE	MODEL	YEAR
SUBARU	LEGACY	2020-2022

---

---

MAKE	MODEL	YEAR
SUBARU	OUTBACK	2020-2022

---

## High-Voltage Batteries May Short Circuit

A short circuit in the battery increases the risk of a fire.

**NHTSA Campaign Number:** 24V215000

**Manufacturer** Porsche Cars North America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 606

### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021-2023 Taycan, Taycan 4 Cross Turismo, 2020-2023 Taycan 4S, Taycan Turbo S, 2021-2022 Taycan 4S Cross Turismo, 2022 Taycan Turbo S Cross Turismo, 2022-2023 Taycan GTS, 2023 Taycan GTS Sport Turismo, and 2020-2021 Taycan Turbo vehicles. The high-voltage battery may experience a short circuit within the battery modules.

### Remedy

Owners are advised to only charge their vehicles to a maximum of 80% battery capacity until the repair has been completed. Dealers will replace the affected modules in the high-voltage battery, free of charge. Owner notification letters are expected to be mailed May 17, 2024. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ARA4.

### Vehicles

---

MAKE	MODEL	YEAR
PORSCHE	TAYCAN	2021-2023
PORSCHE	TAYCAN 4 CROSS TURISMO	2021-2023
PORSCHE	TAYCAN 4S	2020-2023
PORSCHE	TAYCAN 4S CROSS TURISMO	2021-2022

---

MAKE	MODEL	YEAR
PORSCHE	TAYCAN GTS	2022-2023
PORSCHE	TAYCAN GTS SPORT TURISMO	2023
PORSCHE	TAYCAN TURBO	2020-2021
PORSCHE	TAYCAN TURBO S	2020-2023

## High-Voltage Batteries May Short Circuit

A short circuit in the battery increases the risk of a fire.

**NHTSA Campaign Number:** 24V217000

**Manufacturer** Porsche Cars North America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 749

### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021-2024 Taycan, 2020-2024 Taycan 4S, Taycan Turbo, 2021-2023 Taycan 4 Cross Turismo, 2022-2023 Taycan 4S Cross Turismo, Taycan Turbo S Cross Turismo, 2023 Taycan Turbo Cross Turismo, 2022-2024 Taycan GTS, Taycan GTS Sport Turismo, and 2020-2023 Taycan Turbo S vehicles. The high-voltage battery may experience a short circuit within the battery modules.

### Remedy

Owners are advised to only charge their vehicles to a maximum of 80% battery capacity until the repair has been completed. Dealers will analyze the battery data and replace the high-voltage battery modules as necessary, free of charge. Owner notification letters are expected to be mailed May 17, 2024. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ARA4.

### Vehicles

MAKE	MODEL	YEAR
PORSCHE	TAYCAN	2021-2024

MAKE	MODEL	YEAR
PORSCHE	TAYCAN 4 CROSS TURISMO	2021-2023
PORSCHE	TAYCAN 4S	2020-2024
PORSCHE	TAYCAN 4S CROSS TURISMO	2022-2023
PORSCHE	TAYCAN GTS	2022-2024
PORSCHE	TAYCAN GTS SPORT TURISMO	2022-2024
PORSCHE	TAYCAN TURBO	2020-2024
PORSCHE	TAYCAN TURBO S	2020-2023

## High-Voltage Batteries May Short Circuit

A short circuit in a high-voltage battery module increases the risk of a fire.

**NHTSA Campaign Number:** 24V228000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 1,013

### Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022-2024 Audi RS E-Tron GT and E-Tron GT vehicles. The high-voltage battery may experience a short circuit within the battery modules.

### Remedy

Owners are advised to only charge their vehicles to a maximum of 80% battery capacity until the repair has been completed. Dealers will analyze the battery data and replace the high-voltage battery modules as necessary, free of charge. Interim letters notifying owners of the safety risk are expected to be mailed May 21, 2024. Second letters will be mailed once the remedy is available. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 93VN.

## Vehicles

MAKE	MODEL	YEAR
AUDI	E-TRON GT	2022-2024
AUDI	RS E-TRON GT	2022-2024

## High-Voltage Batteries May Short Circuit

A short circuit in a high-voltage battery module increases the risk of a fire.

**NHTSA Campaign Number:** 24V229000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 29

### Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022-2023 Audi RS E-Tron GT and E-Tron GT vehicles. The high-voltage battery may experience a short circuit within the battery modules.

### Remedy

Owners are advised to only charge their vehicles to a maximum of 80% battery capacity until the repair has been completed. Dealers will replace the high-voltage battery modules, free of charge. Interim letters notifying owners of the safety risk are expected to be mailed May 21, 2024. Second letters will be mailed once the remedy is available. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 93VM.

## Vehicles

MAKE	MODEL	YEAR
AUDI	E-TRON GT	2022-2023
AUDI	RS E-TRON GT	2022-2023

## High Beams May Not Activate/FMVSS 108

High beam headlights that do not activate as intended can reduce visibility, increasing the risk of a crash.

**NHTSA Campaign Number:** 24V219000

**Manufacturer** Lamborghini (Automobili Lamborghini)

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 22

### Summary

Lamborghini (Automobili Lamborghini) is recalling certain 2024 Huracan vehicles. The high beam headlights may not activate. As such, these vehicles fails to comply with the requirements of the Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

### Remedy

Dealers will reconfigure the vehicle high beam settings, free of charge. Owner notification letters are expected to be mailed April 26, 2024. Owners may contact Lamborghini customer service at 1-866-681-6276. Lamborghini's number for this recall is L62X-R.02.24.

### Vehicle

---

MAKE	MODEL	YEAR
LAMBORGHINI	HURACAN	2024

---

## Windshield May Detach During A Crash/FMVSS 212

A windshield that detaches from the vehicle during a crash can increase the risk of injury.

**NHTSA Campaign Number:** 24V238000

**Manufacturer** Chrysler (FCA US, LLC) (Stellantis)

**Components** VISIBILITY

**Potential Number of Units Affected** 223

### Summary

Chrysler (FCA US, LLC) is recalling certain 2024 Pacifica and Voyager vehicles. The windshield may not have been properly bonded to the vehicle, allowing it to detach during a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 212, "Windshield Mounting."

## Remedy

Dealers will replace the windshield, free of charge. Owner notification letters are expected to be mailed May 17, 2024. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is 25B.

## Vehicles

MAKE	MODEL	YEAR
CHRYSLER	PACIFICA	2024
CHRYSLER	VOYAGER	2024

## Tires Manufactured Incorrectly

A loss of vehicle handling and control increases the risk of a crash.

**NHTSA Campaign Number:** 24V223000

**Manufacturer** Ford Motor Company

**Components** TIRES

**Potential Number of Units Affected** 115

### Summary

Ford Motor Company (Ford) is recalling certain 2023 Maverick and Bronco Sport vehicles. The tires may have been manufactured incorrectly, which may result in a loss of vehicle handling and control.

### Remedy

Dealers will inspect and replace the tires, as necessary, free of charge. Owner notification letters are expected to be mailed April 1, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S20.

## Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2023
FORD	MAVERICK	2023

