



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

Steering Gear Shaft May Fracture

Fractured steering gear teeth can cause a loss of steering control, increasing the risk of a crash.

NHTSA Campaign Number: 24V233000

Manufacturer PACCAR Incorporated

Components STEERING

Potential Number of Units Affected 782

Summary

PACCAR Incorporated (PACCAR) is recalling certain 2025 Peterbilt 536, 548, 567, 579, and Kenworth T280, T380, T480, T680, T880, and W990 vehicles. The steering gear sector shaft may have been improperly heat-treated, which can cause the gear teeth to crack or fracture.

Remedy

Dealers will inspect the serial numbers, and replace the steering gears as necessary, free of charge. Owner notification letters are expected to be mailed May 26, 2024. Owners may contact Kenworth customer service at 1-425-828-5888 and Peterbilt customer service at 1-940-591-4220. PACCAR's numbers for this recall are 24PBF and 24KWF.

Vehicles

MAKE	MODEL	YEAR
KENWORTH	T280	2025
KENWORTH	T380	2025

MAKE	MODEL	YEAR
KENWORTH	T480	2025
KENWORTH	T680	2025
KENWORTH	T880	2025
KENWORTH	W990	2025
PETERBILT	536	2025
PETERBILT	548	2025
PETERBILT	567	2025
PETERBILT	579	2025

Unintended Deactivation of Traction Control

An inactive traction control system can increase the risk of a crash.

NHTSA Campaign Number: 24V240000

Manufacturer Chrysler (FCA US, LLC) (Stellantis)

Components TRACTION CONTROL SYSTEM

Potential Number of Units Affected 26,776

Summary

Chrysler (FCA US, LLC) is recalling certain 2024 Pacifica and Voyager vehicles. The traction control system (TCS) does not function when cruise control is activated.

Remedy

Dealers will update the TCS software, free of charge. Owner notification letters are expected to be mailed May 17, 2024. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is 22B.

Vehicles

MAKE	MODEL	YEAR
CHRYSLER	PACIFICA	2024
CHRYSLER	VOYAGER	2024

Power Steering Pressure Line May Detach and Leak

A sudden loss of power steering fluid can result in a loss of power steering and power brake assist, increasing the risk of a crash.

NHTSA Campaign Number: 24V245000

Manufacturer Jayco, Inc.

Components STEERING, SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 1,719

Summary

Jayco, Inc. (Jayco) is recalling certain 2020-2022 Entegra Esteem, Odyssey, and Jayco Greyhawk, Redhawk, and Greyhawk Prestige motorhomes. An inadequate connection between the power steering pressure line and the brake hydroboost unit may result in a sudden loss of power steering fluid.

Remedy

Dealers will replace the power steering pressure line and the hydro boost jumper line, free of charge. Owner notification letters are expected to be mailed May 30, 2024. Owners may contact Jayco customer service at 1-800-283-8267.

Vehicles

MAKE	MODEL	YEAR
ENTEGRRA	ESTEEM	2020-2022
ENTEGRRA	ODYSSEY	2020-2022
JAYCO	GREYHAWK	2020-2022

MAKE	MODEL	YEAR
JAYCO	GREYHAWK PRESTIGE	2020-2022
JAYCO	REDHAWK	2020-2022

Front Lower Control Arm May Fail

Front lower control arm failure can cause a sudden loss of steering control, increasing the risk of a crash.

NHTSA Campaign Number: 24V244000

Manufacturer Kia America, Inc.

Components SUSPENSION

Potential Number of Units Affected 215

Summary

Kia America, Inc. (Kia) is recalling certain 2023 Forte vehicles. The right front lower control arm may have been improperly welded, which can cause it to fail.

Remedy

Owners are advised not to drive their vehicles until the repair has been performed. Dealers will replace the right front lower control arm, free of charge. Owner notification letters are expected to be mailed April 17, 2024. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC306. This recall expands previous NHTSA recall number 23V-649.

Vehicle

MAKE	MODEL	YEAR
KIA	FORTE	2023

Obstructed Rearview Camera Image/FMVSS 111

An obstructed rearview camera image reduces rearward visibility and increases the risk of a crash or injury.

NHTSA Campaign Number: 24V246000

Manufacturer Hyundai Motor America

Components BACK OVER PREVENTION

Potential Number of Units Affected 18,206

Summary

Hyundai Motor America (Hyundai) is recalling certain 2024 Santa Fe vehicles. The rearview camera image may be obstructed by a trailer parking assist message. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will update the software for the rearview camera system, free of charge. Owner notification letters are expected to be mailed June 1, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 258.

Vehicle

MAKE	MODEL	YEAR
HYUNDAI	SANTA FE	2024

Turn Signal Malfunction/FMVSS 108

Turn signals that do not function properly may fail to indicate the driver's intention to change vehicle direction, increasing the risk of a crash.

NHTSA Campaign Number: 24V239000

Manufacturer Chrysler (FCA US, LLC) (Stellantis)

Components EXTERIOR LIGHTING, STEERING

Potential Number of Units Affected 12,221

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Cherokee vehicles. The turn signal self-canceling feature may not function properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will inspect and replace the steering column control module as necessary, free of charge. Owner notification letters are expected to be mailed May 17, 2024. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is 24B.

Vehicle

MAKE

MODEL

YEAR

JEEP

CHEROKEE

2022
