



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

July 29, 2024

### Loss of Steering Control from Tie Rod Failure

Tie rod failure can cause a loss of vehicle steering control and increase the risk of a crash.

**NHTSA Campaign Number:** 24V556000

**Manufacturer** Navistar, Inc.

**Components** STEERING

**Potential Number of Units Affected** 532

#### Summary

Navistar, Inc. (Navistar) is recalling certain 2025 International HV, HX, LT, MV, and RH vehicles. The tie rod assemblies may contain ball studs that have been incorrectly heat-treated, which can cause them to break, and possibly result in tie rod failure.

#### Remedy

Dealers will replace the tie rod end and re-align the front axle, free of charge. Owner notification letters are expected to be mailed September 9, 2024. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 24511.

#### Vehicles

---

MAKE	MODEL	YEAR
INTERNATIONAL	HV	2025

---

---

MAKE	MODEL	YEAR
INTERNATIONAL	HX	2025
INTERNATIONAL	LT	2025
INTERNATIONAL	MV	2025
INTERNATIONAL	RH	2025

---

## Vehicle Fire When Parked

A vehicle fire increases the risk of injury.

**NHTSA Campaign Number:** 24V536000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** HYBRID PROPULSION SYSTEM

**Potential Number of Units Affected** 15,910

### Summary

Chrysler (FCA US, LLC) is recalling certain 2017-2018 Pacifica Plug-In Hybrid Electric (PHEV) vehicles that received a software update remedy under NHTSA recall number 22V-077. The battery pack may cause a vehicle fire when parked, even with the ignition in the "Off" position.

### Remedy

Owners are advised not to charge their vehicles, and to park outside and away from structures, until they are repaired. Dealers will update the high voltage battery pack control module (BPCM) software. In addition, dealers will inspect and if necessary, replace the battery pack assembly. Repairs will be performed free of charge. Owner notification letters are expected to be mailed September 6, 2024. Owners may contact FCA US LLC customer service at 1-800-853-1403. FCA US LLC's number for this recall is 73B. Vehicles previously repaired under recall 22V-077 will need to have the new remedy completed.

### Vehicle

---

MAKE	MODEL	YEAR
CHRYSLER	PACIFICA HYBRID	2017-2021

---

## Right Front Lower Control Arm May Fracture

A right front lower control arm fracture can cause loss of vehicle control, increasing the risk of a crash.

**NHTSA Campaign Number:** 24V540000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** SUSPENSION

**Potential Number of Units Affected** 39

### Summary

Honda (American Honda Motor Co.) is recalling certain 2024 Prologue vehicles. The right front lower control arm may contain a manufacturing defect that can cause it to fracture.

### Remedy

Dealers will inspect and replace the right front lower control arm as necessary, free of charge. Owner notification letters are expected to be mailed September 2, 2024. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is PIY.

### Vehicle

MAKE	MODEL	YEAR
HONDA	PROLOGUE	2024

## Seat Back Malfunction

The seat back could release when force is applied to the shoulder belt, increasing the risk of injury during a crash.

**NHTSA Campaign Number:** 24V552000

**Manufacturer** A&J Vans Inc

**Components** SEATS

**Potential Number of Units Affected** 6

### Summary

A&J Vans Inc (A&J) is recalling certain 2024 Ford Transit vehicles, equipped with certain GO-ES Space Saver Foldaway Seats. The recliner mechanism may not engage when the seat back is fully reclined.

### Remedy

A&J will inspect and repair the seats as necessary, free of charge. Owners may contact A&J customer service at 920-775-9333.

## Vehicle

---

MAKE	MODEL	YEAR
FORD	TRANSIT	2023

---

## Loss of Power Steering Assist

A loss of power steering assist can increase the risk of a crash.

**NHTSA Campaign Number:** 24V542000

**Manufacturer** Ford Motor Company

**Components** STEERING

**Potential Number of Units Affected** 1,902

### Summary

Ford Motor Company (Ford) is recalling certain 2023-2024 Transit vehicles equipped with a Transit Trail package. The electronic power assist steering (EPAS) ground eyelet joint may experience corrosion, which can result in a loss of power steering assist.

### Remedy

Dealers will install a new EPAS ground pigtail kit, free of charge. Owner notification letters are expected to be mailed August 5, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S46.

## Vehicle

---

MAKE	MODEL	YEAR
FORD	TRANSIT	2023-2024

---

## Rear Tire Tread Separation May Cause Crash

Tread separation may cause a loss of vehicle control, increasing the risk of a crash.

**NHTSA Campaign Number:** 24V535000

**Manufacturer** Suzuki Motor USA, LLC

**Components** TIRES

## Potential Number of Units Affected 1,688

### Summary

Suzuki Motor USA, LLC (Suzuki) is recalling certain 2023-2024 DL800DE motorcycles. The rear tire may crack or deform, resulting in tire tread separation.

### Remedy

Owners are advised not to ride their motorcycles until the remedy has been completed. The remedy is currently under development. Owner notification letters are expected to be mailed July 26, 2024. Owners may contact Suzuki customer service at 1-714- 572-1490. Suzuki's number for this recall is 3A03.

### Vehicle

---

MAKE	MODEL	YEAR
SUZUKI	DL800	2023-2024

---