



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

August 26, 2024

High Voltage Battery May Short Circuit

A short circuit increases the risk of a fire.

NHTSA Campaign Number: 24V612000

Manufacturer BMW of North America, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 12,535

Summary

BMW of North America, LLC. (BMW) is recalling certain 2020-2024 MINI Hardtop 2 Door (Cooper SE) vehicles. Faults may occur in the high voltage battery or high voltage system, resulting in a short circuit.

Remedy

Dealers will provide a software update, free of charge. Owner notification letters are expected to be mailed October 7, 2024. Owners may contact BMW customer service at 1-866-ASK-MINI (1-866-275-6464).

Vehicle

MAKE	MODEL	YEAR
MINI	COOPER SE	2020-2024

Water Pump Connector May Short Circuit

An electrical short increases the risk of a fire.

NHTSA Campaign Number: 24V608000

Manufacturer BMW of North America, LLC

Components ENGINE AND ENGINE COOLING, ELECTRICAL SYSTEM

Potential Number of Units Affected 720,796

Summary

BMW of North America, LLC. (BMW) is recalling certain 2012-2015 X1 sDrive28i, X1 xDrive28i, 2012-2016 Z4 sDrive28i, 528i, 528i xDrive, 328i, 328xi, 2016-2018 X5 xdrive 40e, 2014-2016 228i, 228xi, 428i, 428i xDrive, 328xi Gran Turismo, 2013-2017 X3 sDrive28i, X3 xDrive28i, 2015-2018 X4 xDrive28i, 2015-2016 428xi vehicles. An improperly sealed electrical connector on the water pump may be exposed to water and short circuit.

Remedy

Dealers will inspect and replace the water pump and plug connector as necessary, and install a protective shield, free of charge. Owner notification letters are expected to be mailed October 4, 2024. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	228I	2014-2016
BMW	228XI	2014-2016
BMW	328I	2012-2016
BMW	328XI	2012-2016
BMW	428I	2014-2016
BMW	428XI	2015-2016
BMW	528I	2012-2016

MAKE	MODEL	YEAR
BMW	X1	2012-2015
BMW	X3	2013-2017
BMW	X4	2015-2018
BMW	X5	2016-2018
BMW	Z4	2012-2016

Loss of Brakes from Unexpected ABS Activation

A release of brake pressure can cause a loss of braking ability, increasing the risk of a crash.

NHTSA Campaign Number: 24V614000

Manufacturer Honda (American Honda Motor Co.)

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 5,031

Summary

Acura (American Honda Motor Co.) is recalling certain 2024 Acura ZDX All-Wheel Drive vehicles. The anti-lock brake system (ABS) may activate unexpectedly and release brake pressure in the vehicle's service brake system.

Remedy

The electronic brake control module software will be updated through an over-the-air (OTA) update or by a dealer, free of charge. Owner notification letters are expected to be mailed September 23, 2024. Owners may contact Acura customer service at 1-800-382-2238. Acura's number for this recall is UJE.

Vehicle

MAKE	MODEL	YEAR
ACURA	ZDX	2024

Brake Pedal May Detach from Brake Booster

Brake pedal detachment can cause a loss of brake function and increase the risk of a crash.

NHTSA Campaign Number: 24V621000

Manufacturer Volkswagen Group of America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 206

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2019 Audi E-Tron Quattro vehicles. The fastener that connects the brake pedal and the brake booster may have been improperly assembled during manufacturing, which can cause the brake pedal to detach from the brake booster.

Remedy

Dealers will replace the brake booster, free of charge. Owner notification letters are expected to be mailed on October 18, 2024. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 46P6.

Vehicle

MAKE	MODEL	YEAR
AUDI	E-TRON	2019
