

NHTSA Recalls of Interest February 6, 2016

RECALL Subject: Label Missing Instruction Manual Information

Report Receipt Date: MAR 18, 2015 NHTSA Campaign Number: 15C001000

Component(s): CHILD SEAT

Potential Number of Units Affected: 31,838

Child Restraints Brand Name	Model	Production Dates	
• GRACO	CLASSIC RIDE	04/01/2014 - 11/30/2014	
 GRACO 	COMFORTSPORT	03/01/2014 - 02/28/2015	
 GRACO 	READY RIDE	11/01/2014 - 02/28/2015	

Manufacturer: Graco Children's Products Inc.

SUMMARY:

Graco Children's Products Inc. (Graco) is recalling certain ComfortSport child restraints, model numbers 1813040 and 1794333; Ready Ride child restraints, model numbers 1924520 and 1924519; and Classic Ride child restraints, model number 1812930. These seats were manufactured between March 1, 2014, and February 28, 2015. The affected convertible child restraints are missing a statement on the affixed label that informs of location of the instruction manual. Without the notice on the fixed label, these seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard No. 213 "Child Restraint Systems."

CONSEQUENCE:

If the label does not inform the seat owner of the instruction manual's location, the owner may not be able to refer to it and may use the seat improperly, increasing the risk of injury to the child in the event of a crash.

REMEDY:

Graco will notify the registered owners and will mail them corrected labels to affix to the child restraints. The recall is expected to begin February 22, 2016.

RECALL Subject: Incorrect Position of Reclining Label/FMVSS 213

Report Receipt Date: FEB 02, 2016 NHTSA Campaign Number: 16C002000 Component(s): CHILD SEAT, EQUIPMENT Potential Number of Units Affected: 15,064

Child Restraints Brand Name Model Production Dates

• GRACO EXTEND2FIT CONVERTIBLE 11/27/2015 - 01/20/2016

Manufacturer: Graco Children's Products Inc.

SUMMARY:

Graco Children's Products, Inc. (Graco) is recalling certain Extend2Fit Convertible child seats manufactured November 27, 2015, to January 20, 2016. The affected child seats may have the recline label affixed at the wrong location, resulting in confusion about how to use the seat properly. As such, these child seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 213, "Child Restraint Systems."

CONSEQUENCE:

If the instructions are followed as shown, a rear-facing infant could be placed in an upright position and/or a forward-facing toddler could be placed in a recline position. Either scenario may increase the risk of injury to the child in the event of a crash.

REMEDY:

Graco will notify owners and provide a new corrected label with application instructions, free of charge. The recall is expected to begin February 26, 2016.