

# NHTSA Recalls of Interest

July 4, 2016

# **RECALL Subject: Air Bag Control Unit Power Supply Corrosion**

**Report Receipt Date:** MAY 27, 2016 **NHTSA Campaign Number:** 16V376000

Component(s): AIR BAGS

**Potential Number of Units Affected: 8,381** 

Vehicle Make	Model	Model Year(s)
• AUDI	A4	2008-2009
• AUDI	A5	2008-2009
• AUDI	Q5	2008-2009

Manufacturer: Volkswagen Group of America, Inc.

#### **SUMMARY:**

Volkswagen Group of America, Inc. (VW) is recalling certain model year 2008-2009 Audi A4, A5, and Q5 vehicles. In the affected vehicles, the Continental air bag control units may corrode and fail.

### **CONSEQUENCE:**

If the air bag control unit fails, the air bags may not deploy in the event of a crash, increasing the risk of occupant injury.

**REMEDY:**Audi will notify owners, and dealers will replace the air bag control unit, free of charge. The manufacturer has not yet provided a notification schedule.

## RECALL Subject: Super High Roof Vehicles Missing Crash Pads

**Report Receipt Date:** MAY 24, 2016 **NHTSA Campaign Number:** 16V351000

**Component(s):** STRUCTURE

**Potential Number of Units Affected:** 3

Vehicle Make	Model	Model Year(s)
<ul> <li>FREIGHTLINER</li> </ul>	SPRINTER 2500	2015-2016
<ul> <li>FREIGHTLINER</li> </ul>	SPRINTER 3500	2015-2016
<ul> <li>MERCEDES BENZ</li> </ul>	SPRINTER 2500	2015-2016
<ul> <li>MERCEDES BENZ</li> </ul>	SPRINTER 3500	2015-2016

Manufacturer: Daimler Vans USA, LLC

#### **SUMMARY:**

Daimler Vans USA, LLC (DVUSA) is recalling certain model year 2015-2016 Mercedes-Benz Sprinter 2500 and 3500 vehicles manufactured May 31, 2015, to April 30, 2016, and 2015-2016 Freightliner Sprinter 2500 and 3500 vehicles manufactured May 1, 2015, to April 30, 2016. The affected vehicles are configured to have super-high roofs, but may not be equipped with the required crash pads.

## **CONSEQUENCE:**

If the required crash pads are missing, it can increase the risk of injury to a front passenger seat occupant if they are unbelted.

#### **REMEDY:**

DVUSA will notify owners, and dealers will install the required crash-pads, free of charge. The recall is expected to begin in June 2016.