

NHTSA Recalls of Interest

May 7, 2012

Report Date :May 7, 2012 at 12:52 PM NHTSA CAMPAIGN ID Number:12V197000

Vehicle Make / Model:Model Year(s):CHRYSLER / 3002011-2012DODGE / CHARGER2011-2012

Manufacturer: CHRYSLER GROUP LLCMfr's Report Date: MAY 01, 2012NHTSA CAMPAIGN ID Number: 12V197000NHTSA Action Number: N/A

Component: SERVICE BRAKES, AIR:ANTILOCK:CONTROL UNIT/MODULE

Potential Number of Units Affected: 119,072

Summary:

CHRYSLER IS RECALLING CERTAIN MODEL YEAR 2011 AND 2012 300 AND DODGE CHARGER VEHICLES. THESE VEHICLES MAY LOSE ABS/ESC SYSTEM FUNCTION DUE TO AN OVERHEATED POWER DISTRIBUTION CENTER.

Consequence:

THIS COULD LEAD TO LOSS OF VEHICLE CONTROL, INCREASING THE RISK OF A CRASH. Remedy:

CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL RELOCATE THE ABS/ESC SYSTEM FUSE, FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING MAY 2012. OWNERS MAY CONTACT CHRYSLER AT 1-800-853-1403.