

NHTSA Recalls of Interest

June 19, 2017

Inadvertent Air Bag Deployment due to Chafed Wire

NHTSA Campaign Number: 17V376000

Manufacturer Chrysler (FCA US LLC)

Components AIR BAGS

Potential Number of Units Affected 209,135

Summary

Chrysler (FCA US LLC) is recalling certain 2011-2012 Dodge Grand Caravan vehicles. In the affected vehicles, the driver's frontal air bag may unexpectedly deploy if the air bag wiring harness gets chafed within the steering wheel and short circuits.

Remedy

Chrysler will notify owners, and dealers will inspect the air bag wiring within the steering wheel, replacing it if necessary. A protective cover will also be installed. These repairs will be made free of charge. The recall is expected to begin July 28, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T33.

Vehicle

MAKE MODEL YEAR

DODGE GRAND CARAVAN 2011-2012

Seatbelt Component may Detach and Enter the Cabin

NHTSA Campaign Number: 17V370000

Manufacturer Volvo Car USA LLC

Components SEAT BELTS

Potential Number of Units Affected 1,305

Summary

Volvo Car USA LLC (Volvo) is recalling certain 2017 XC90 vehicles. The Micro Gas Generator (MGG), a subcomponent part used within the right hand side seat belt retractor for the third row seats, may detach after the Autoliv seatbelt retractor pretensioner is deployed.

Remedy

Volvo will notify owners, and dealers will replace the third row passenger's side seatbelt retractor, free of charge. The recall is

expected to begin August 7, 2017. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R89716.

Vehicle

MAKE MODEL YEAR

VOLVO XC90 2017