



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

June 26, 2017

Loss of Electric Power Steering Assist

NHTSA Campaign Number: 17V382000

Manufacturer General Motors LLC

Components STEERING

Potential Number of Units Affected 6,204

Summary

General Motors LLC (GM) is recalling certain 2014-2016 Chevrolet SS vehicles. Corrosion of the connector between the Mando electric power steering module and the torque sensor connector may cause a loss of electric power steering assist.

Remedy

GM will notify owners, and dealers will inspect the steering gear assembly, replacing it as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners

may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is 17248.

Vehicle

MAKE MODEL YEAR

CHEVROLET SS 2014-2016