

NHTSA Recalls of Interest April 2, 2018

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V188000

Manufacturer Ferrari North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 1,870

Summary

Ferrari North America, Inc. (Ferrari) is recalling certain 2009-2011 Ferrari California, and 2010-2011 Ferrari 458 Italia vehicles that have not had their passenger frontal air bag replaced. These passenger frontal air bag modules have air bag inflators that may explode in the event of a crash due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Ferrari will notify owners, and dealers will replace the passenger frontal air bag assembly with one that uses an alternate inflator, free of charge. The recall is expected to begin in March 2018. Owners may contact Ferrari customer service at 1-201-816-2668. Ferrari's number for this recall is 60A. Note: This recall supersedes recall 16V-341.

Vehicles

MAKE MODEL YEAR

FERRARI 458 ITALIA 2010-2011 FERRARI CALIFORNIA 2009-2011