



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

August 27, 2018

Passenger Air Bag Incorrectly Manufactured

NHTSA Campaign Number: 18V533000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 3

Summary

BMW of North America, LLC (BMW) is recalling one each of 2019 BMW 430i xDrive Gran Coupe, 440i xDrive Gran Coupe and 430i xDrive Convertible vehicles. The ZF front passenger air bag inflator may have been incorrectly manufactured, potentially affecting the air bag deployment performance in the event of a crash.

Remedy

All affected vehicles are still in dealer inventory. Dealers will replace the front passenger air bag module, free of charge.

Vehicles

MAKE MODEL YEAR

BMW 430I 2019

MAKE MODEL YEAR

BMW 440I 2019

Insufficient Coating on Rear Brake Caliper Pistons

NHTSA Campaign Number: 18V523000

Manufacturer Chrysler (FCA US LLC)

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 154,335

Summary

Chrysler (FCA US LLC) is recalling certain 2018-2019 Dodge Grand Caravan and Jeep Compass, 2018 Dodge Journey, and 2019 Jeep Cherokee vehicles. The ZF rear brake caliper pistons on these vehicles may have an insufficient coating causing gas pockets to form, potentially reducing rear brake performance.

Remedy

Chrysler will notify owners, and dealers will bleed the vehicle's brake system, free of charge. The recall is expected to begin September 28, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U86.

Vehicles

MAKE	MODEL	YEAR
DODGE	GRAND CARAVAN	2018-2019
DODGE	JOURNEY	2018
JEEP	CHEROKEE	2019
JEEP	COMPASS	2018-2019

Voltage Regulator may Fail and Cause Stall

NHTSA Campaign Number: 18V524000

Manufacturer Chrysler (FCA US LLC)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 12,779

Summary

Chrysler (FCA US LLC) is recalling certain 2018 Jeep Renegade, Compass and Grand Cherokee, RAM 1500 and Promaster, Fiat 500x, Dodge Journey, Challenger, Charger and Durango and Chrysler 300x vehicles, 2017-2018 Jeep Wrangler, Dodge Grand Caravan and Chrysler Town and Country vehicles and 2018-2019 Jeep Cherokee and Chrysler Pacifica vehicles. The Continental powertrain control module may be equipped with a voltage regulator chip in the circuit board that may fail, causing a stall or a no start condition.

Remedy

Chrysler will notify owners, and dealers will replace the powertrain control module, free of charge. The recall is expected to begin September 28, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U87.

Vehicles

MAKE	MODEL	YEAR
CHRYSLER	300	2018
CHRYSLER	PACIFICA	2018-2019
CHRYSLER	TOWN AND COUNTRY	2017-2018
DODGE	CHALLENGER	2018
DODGE	CHARGER	2018
DODGE	DURANGO	2018
DODGE	GRAND CARAVAN	2017-2018
DODGE	JOURNEY	2018
FIAT	500X	2018
JEEP	CHEROKEE	2018-2019
JEEP	COMPASS	2018
JEEP	GRAND CHEROKEE	2018
JEEP	RENEGADE	2018
JEEP	WRANGLER	2017-2018
RAM	1500	2018
RAM	PROMASTER	2018