

# NHTSA Recalls of Interest August 6, 2018

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V452000

Manufacturer Nissan North America, Inc.

**Components** AIR BAGS

# **Potential Number of Units Affected** 233

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2007-2008 Nissan Versa sedan and Versa hatchback vehicles originally sold, or ever registered, in Alabama, Arizona, Arkansas, California, Delaware, District of Columbia, Florida, Georgia, Hawaii, Illinois, Indiana, Kansas, Kentucky, Louisiana, Maryland, Mississippi, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, South Carolina, Tennessee, Texas, Virginia, West Virginia, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands.

The passenger air bag inflators may explode due to propellant degradation due to exposure to humidity and temperature cycling.

# Remedy

Nissan will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall began July 25, 2018. Owners may contact Nissan customer service at 1-800-867-7669. Note: The vehicles covered by this recall are in addition to those covered by recall 16V-349.

# Vehicle

# MAKE MODEL YEAR

NISSAN VERSA 2007-2008

# Tailgate May Open Unexpectedly

NHTSA Campaign Number: 18V486000

Manufacturer Chrysler (FCA US LLC)

## Components STRUCTURE, LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 1,149,237

## Summary

Chrysler (FCA US LLC) is recalling certain 2015-2017 RAM 1500, 2500, and 3500 pickup trucks equipped with a power locking tailgate and either a 5 foot, 7 inch or 6 foot, 4 inch bed. The ADAC Plastic tailgate actuator limiter tab may fracture and cause the tailgate to unlatch and open while driving.

## Remedy

Chrysler will notify owners, and dealers will repair the vehicle, free of charge. The recall is expected to begin September 14, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U74.

## Vehicles

## MAKE MODEL YEAR

RAM	1500	2015-2017
RAM	2500	2015-2017
RAM	3500	2015-2017