



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 6, 2019

Passenger Seat Mounting Bolts may be Loose

NHTSA Campaign Number: 19V248000

Manufacturer Chrysler (FCA US LLC)

Components SEATS

Potential Number of Units Affected 253

Summary

Chrysler (FCA US LLC) is recalling certain 2019 Jeep Cherokee vehicles. The front passenger seat mounting bolts may be loose.

Remedy

Chrysler has notified owners, and dealers will tighten the mounting bolts, free of charge. The recall began April 11, 2019. Owners may contact FCA US customer service at 1-800-853-1403. Chrysler's number for this recall is V31.

Vehicle

MAKE MODEL YEAR

JEEP CHEROKEE 2019

Sun Visors May Lack Air Bag Warning Information

NHTSA Campaign Number: 19V246000

Manufacturer Chrysler (FCA US LLC)

Components AIR BAGS

Potential Number of Units Affected 1,097

Summary

Chrysler (FCA US LLC) is recalling certain 2019 Dodge Charger vehicles. The driver and passenger sun visors may lack the required air bag warning information. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

Remedy

Chrysler has notified owners, and dealers will replace the driver and passenger sun visors, free of charge. The recall began April 17, 2019. Owners may contact FCA US customer service at 1-800-853-1403. Chrysler's number for this recall is V35.

Vehicle

MAKE MODEL YEAR

DODGE CHARGER 2019

Brake Lights May Remain Illuminated

NHTSA Campaign Number: 19V235000

Manufacturer Nissan North America, Inc.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 5,744

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2019 Nissan Altima vehicles. The brake switch bracket may be in the incorrect location, which may cause the brake switch to remain on.

Remedy

Nissan will notify owners, and dealers will inspect and install a new brake pedal as needed, free of charge. The recall is expected to begin in May 2019. Owners may contact Nissan customer service at 1-800-867-7669.

Vehicle

MAKE MODEL YEAR

NISSAN ALTIMA 2019

Engine Block Heater/Terminal Short-Circuit

NHTSA Campaign Number: 19V328000

Manufacturer General Motors LLC

Components ENGINE

Potential Number of Units Affected 324,226

Summary

General Motors LLC (GM) is recalling certain 2019 Chevrolet Silverado 4500, 5500 and 6500 vehicles and 2017-2019 Chevrolet Silverado 2500 and 3500 vehicles and GMC Sierra 2500 and 3500 vehicles equipped with Duramax 6.6 liter diesel engines and an optional engine-block heater. The engine block heater cord or the terminals that connect the heater cord to the block heater may short circuit and fail.

Remedy

The remedy for this recall is still under development. The manufacturer has not yet provided a notification schedule. Owners may contact GM customer service at 1-586-596-1733. GM's number for this recall is N182206310.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO 2500	2017-2019
CHEVROLET	SILVERADO 3500	2017-2019
CHEVROLET	SILVERADO 4500HD	2019
CHEVROLET	SILVERADO 5500HD	2019
CHEVROLET	SILVERADO 6500HD	2019
GMC	SIERRA 2500	2017-2019
GMC	SIERRA 3500	2017-2019