



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

February 24, 2020

ABS Module May Short Circuit

NHTSA Campaign Number: 20V088000

Manufacturer Kia Motors America

Components SERVICE BRAKES, HYDRAULIC, ELECTRICAL SYSTEM

Potential Number of Units Affected 228,829

Summary

Kia Motors America (Kia) is recalling certain 2006-2010 Sedona and 2007-2009 Sorento vehicles. Moisture may enter the Anti-lock Brake (ABS) Module and result in an electrical short.

Remedy

Kia will notify owners, and dealers will install a relay in the main junction box to prevent power from being directed to the HECU when the vehicle's ignition switch is turned off, free of charge. The recall is expected to begin April 10, 2020. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC186.

Vehicles

MAKE MODEL YEAR

KIA SEDONA 2006-2010

KIA SORENTO 2007-2009

