



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 11, 2020

[Seatbelt may not Restrain Occupant/FMVSS 209](#)

NHTSA Campaign Number: 20V250000

Manufacturer National Van Builders, Inc.

Components SEAT BELTS

Potential Number of Units Affected 5

Summary

National Van Builders, Inc. (National Van Builders) is recalling certain vehicles based on 2019-2020 Ford Transit and 2019 Ram Promaster vans equipped with Freedman GO-ES foldaway seats. The seat belt retractor block out zone may have not been set correctly, potentially resulting in a seat belt that may not properly secure the occupant. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 209, "Seat Belt Assemblies."

Remedy

National Van Builders will notify owners, and dealers will replace the retractors, free of charge. The recall is expected to begin May 26, 2020. Owners may contact Freedman customer service at 1-800-443-4540 or National Van Builders customer service at 1-800-527-7477.

Vehicles

MAKE	MODEL	YEAR
FORD	TRANSIT	2019-2020

MAKE MODEL YEAR

RAM PROMASTER 2019

Driver's Air Bag May Be Insufficiently Tightened

NHTSA Campaign Number: 20V248000

Manufacturer Hyundai Motor America

Components AIR BAGS

Potential Number of Units Affected 1,295

Summary

Hyundai Motor America (Hyundai) is recalling certain 2016 Genesis Coupe vehicles. The mounting bolts securing the driver-side frontal air bag may have been insufficiently tightened, potentially causing the air bag to detach from the steering wheel.

Remedy

Hyundai will notify owners, and dealers will inspect the mounting bolts and retighten them as necessary, free of charge. The recall is expected to begin June 26, 2020. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 192.

Vehicle

MAKE MODEL YEAR

HYUNDAI GENESIS COUPE 2016

Head Air Bag Inflator Humidity Exceeds Specs

NHTSA Campaign Number: 20V243000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 33

Summary

BMW of North America, LLC (BMW) is recalling certain 2017 530i, 530i xDrive, 540i and 540i xDrive and 2017-2018 530e xDrive vehicles. Prior exposure to excessive levels of humidity within the driver and passenger head air bag inflators may affect the proper deployment of the head air bags.

Remedy

BMW will notify owners, and dealers will replace the left or right head air bag, free of charge. The recall is expected to begin June 22, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

BMW	530E	2017-2018
BMW	530I	2017
BMW	540I	2017

Seat Belts Do Not Extend/FMVSS 208, 209

NHTSA Campaign Number: 20V242000

Manufacturer Motor Coach Industries

Components SEAT BELTS

Potential Number of Units Affected 1,276

Summary

Motor Coach Industries (MCI) is recalling certain 2015-2016 D4000, 2015-2020 D4500 and D4505, 2016-2020 J4500, 2018 J3500, and 2017 D4005 buses. The seat belts may not extend from the retracted position, rendering the seat belt unusable. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standards (FMVSS) number 208, "Occupant Crash Protection," and number 209, "Seat Belt Assemblies."

Remedy

MCI will notify the affected owners, and dealers will inspect and replace the seat belts, as necessary, free of charge. The recall is expected to begin May 29, 2020. Owners may contact MCI customer service at 1-800-241-2947. MCI's number for this recall is SB 482.

Vehicles

MAKE MODEL YEAR

MCI	D4000	2015-2016
MCI	D4005	2017
MCI	D4500	2015-2020
MCI	D4505	2015-2020
MCI	J3500	2018
MCI	J4500	2016-2020

Improperly Assembled SeatBelt Retractors/FMVSS 209

NHTSA Campaign Number: 20V237000

Manufacturer Forest River, Inc.

Components SEAT BELTS

Potential Number of Units Affected 2

Summary

Forest River, Inc. (Forest River) is recalling certain 2020 StarTrans P/S2 ST93036 transit buses equipped with Freedman GO-ES foldaway seats. The seat belt retractor block out zone may have not been set correctly, potentially resulting in a seat belt that may not properly secure the occupant. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 209, "Seat Belt Assemblies."

Remedy

Forest River will notify the vehicle owners, and dealers will inspect and replace the retractors, free of charge. The recall is expected to begin June 7, 2020. Owners may contact Forest River customer service at 1-800-348-7440 or Freedman Seating customer service at 1-800-443-4540. Forest River's number for this recall is 05-1158.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

STARTRANS PS2	2020
---------------	------