



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 25, 2020

[Passenger Air Bag may Deploy Improperly](#)

NHTSA Campaign Number: 20V273000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 3,024

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019 Audi Q3 vehicles. The passenger air bag may not properly deploy through the instrument panel tear seam.

Remedy

Audi will notify owners, and dealers will inspect the instrument panel and replace it, if necessary, free of charge. The recall is expected to begin June 12, 2020. Owners may contact Audi customer service at 1-800-822-2834. Volkswagen's number for this recall is 70H7.

Vehicle

MAKE MODEL YEAR

AUDI Q3 2019

Improper deployment of Passenger Air Bag

NHTSA Campaign Number: 20V274000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 153

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2020 Audi A6, A6 Allroad and A7 vehicles. The passenger air bag may not properly deploy through the instrument panel tear seam.

Remedy

Audi will notify owners, and dealers will replace the instrument panels, free of charge. The recall is expected to begin July 10, 2020. Owners may contact Audi customer service at 1-800-822-2834. Volkswagen's number for this recall is 70H6.

Vehicles

MAKE MODEL YEAR

AUDI	A6	2020
AUDI	A7	2020
AUDI	ALLROAD	2020

Incorrectly Assembled Rear Seat Belt Assembly

NHTSA Campaign Number: 20V280000

Manufacturer Mitsubishi Motors North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 3,238

Summary

Mitsubishi Motors North America, Inc. (MMNA) is recalling certain 2019-2020 Outlander and 2019 Outlander PHEV vehicles. The seat belt for the right side second-row seat may have been assembled incorrectly.

Remedy

MMNA will notify owners, and dealers will inspect the right side second-row seat belt and replace it as necessary, free of charge. This recall is expected to begin July 14, 2020. Owners may contact MMNA customer service at 1-888-648-7820. MMNA's number for this recall is SR-20-002.

Vehicles

MAKE	MODEL	YEAR
MITSUBISHI	OUTLANDER	2019-2020
MITSUBISHI	OUTLANDER PHEV	2019

Out Of Park Warning Message and Chime Too Short

NHTSA Campaign Number: 20V263000

Manufacturer Ford Motor Company

Components POWER TRAIN, ELECTRICAL SYSTEM

Potential Number of Units Affected 10,460

Summary

Ford Motor Company (Ford) is recalling certain 2019 Expedition and 2019-2020 Mustang vehicles. The "Transmission Not In Park" warning message and associated chime duration are shorter than intended.

Remedy

Ford will notify owners, and dealers will reprogram the instrument cluster, free of charge. The recall is expected to begin May 25, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S21.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPEDITION	2019
FORD	MUSTANG	2019-2020