

NHTSA Recalls of Interest September 28, 2020

Seatbelt Tension Sensor Malfunction

NHTSA Campaign Number: 20V574000

Manufacturer Ford Motor Company

Components SEAT BELTS

Potential Number of Units Affected 123

Summary

Ford Motor Company (Ford) is recalling certain 2020 Expedition vehicles. The seat belt tension sensor may incorrectly classify a child occupant as an adult.

Remedy

Ford will notify owners, and dealers will replace the seat belt buckle, free of charge. The recall is expected to begin October 12, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S54.

Vehicle

MAKE MODEL YEAR

FORD EXPEDITION 2020

Brake Pedal Bracket May Facture

NHTSA Campaign Number: 20V573000

Manufacturer Ford Motor Company

Components SERVICE BRAKES, HYDRAULIC, SERVICE BRAKES

Potential Number of Units Affected 38,005

Summary

Ford Motor Company (Ford) is recalling certain 2020 Mustang vehicles equipped with automatic transmissions. The brake pedal bracket may fracture during sudden stopping.

Remedy

Ford will notify owners, and dealers will replace the brake pedal bracket assembly, free of charge. The recall is expected to begin November 16, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S52.

Vehicle

MAKE MODEL YEAR

FORD MUSTANG 2020