



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest June 3, 2021

### Driver's Seatbelt Assembly Malfunction

**NHTSA Campaign Number:** 21V377000

**Manufacturer** Ford Motor Company

**Components** SEAT BELTS

**Potential Number of Units Affected** 82

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2021 Edge vehicles. The driver's seat belt retractor pretensioner assembly may not function correctly when activated during a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

#### **Remedy**

Dealers will replace the driver's seat belt retractor pretensioner assembly, free of charge. Owner notification letters are expected to be mailed June 14, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21C13.

#### **Vehicle**

##### **MAKE MODEL YEAR**

FORD EDGE 2021

## Engine Control Module Calibrated Incorrectly

**NHTSA Campaign Number:** 21V346000

**Manufacturer** General Motors, LLC

**Components** ENGINE AND ENGINE COOLING

**Potential Number of Units Affected** 196

### **Summary**

General Motors, LLC (GM) is recalling certain 2019-2020 Chevrolet 6500HD vehicles. The engine control module (ECM) was calibrated incorrectly, allowing the vehicle to exceed the tires' maximum speed rating of 75 mph.

### **Remedy**

Dealers will update the ECM software, free of charge. Owner notification letters are expected to be mailed June 28, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N202325530.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

CHEVROLET	SILVERADO 6500HD	2019-2020
-----------	------------------	-----------

## Fuel Pump Module Can Fail and Cause a Stall

**NHTSA Campaign Number:** 21V373000

**Manufacturer** Nissan North America, Inc.

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 24,140

### **Summary**

Nissan North America, Inc. (Nissan) is recalling certain 2020-2021 Nissan Armada and 2020-2021 INFINITI QX80 vehicles equipped with V8 engines. The impeller can swell and bind within the fuel pump module, causing it to fail.

## **Remedy**

Dealers will replace the fuel pump module, free of charge. Owner notification letters are expected to be mailed July 20, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is R21A2. Owners may contact INFINITI customer service at 1-800-662-6200. INFINITI's number for this recall is R21A3.

## **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

INFINITI	QX80	2020-2021
----------	------	-----------

NISSAN	ARMADA	2020-2021
--------	--------	-----------