



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest June 28, 2021

Loss of Power Steering Assist

NHTSA Campaign Number: 21V455000

Manufacturer General Motors, LLC

Components STEERING

Potential Number of Units Affected 26,847

Summary

General Motors, LLC (GM) is recalling certain 2021 Cadillac Escalade, Escalade ESV, Chevrolet Suburban, Chevrolet Tahoe, GMC Yukon, and Yukon XL vehicles. A software issue may cause a loss of power steering assist at startup or while driving.

Remedy

The power steering module software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed August 2, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020; Cadillac customer service at 1-800-458-8006; or GMC customer service at 1-800-462-8782. GM's number for this recall is N212333900.

Vehicles

MAKE	MODEL	YEAR
CADILLAC	ESCALADE	2021
CADILLAC	ESCALADE ESV	2021
CHEVROLET	SUBURBAN	2021

MAKE	MODEL	YEAR
CHEVROLET	TAHOE	2021
GMC	YUKON	2021
GMC	YUKON XL	2021

Rearview Camera Image May Not Display/FMVSS 111

NHTSA Campaign Number: 21V466000

Manufacturer Lamborghini (Automobili Lamborghini)

Components BACK OVER PREVENTION

Potential Number of Units Affected 2,701

Summary

Lamborghini (Automobili Lamborghini) is recalling certain 2018-2021 Huracan vehicles. In temperatures below 41°F, the rearview camera may not display due to a software error in the infotainment system. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

Dealers will update the instrument cluster software, free of charge. Owner notification letters are expected to be mailed August 6, 2021. Owners may contact Lamborghini customer service at 1-866-681-6276. Lamborghini's number for this recall is L62X-R.01.21.

Vehicle

MAKE	MODEL	YEAR
LAMBORGHINI	HURACAN	2018-2021

Tie Rods May Be Bent

NHTSA Campaign Number: 21V461000

Manufacturer Nissan North America, Inc.

Components STEERING

Potential Number of Units Affected 138,736

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2020-2021 Sentra vehicles. The left and/or right tie rod may be bent.

Remedy

Dealers will inspect and replace the left and/or right tie rods as necessary, free of charge. Owner notification letters are expected to be mailed August 5, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PM985.

Vehicle

MAKE MODEL YEAR

NISSAN SENTRA 2020-2021