

# NHTSA Recalls of Interest September 28, 2021

## Child Seat Webbing May Fail/FMVSS 213

NHTSA Campaign Number: 21C001000

Manufacturer Combi USA, Inc.

**Components** CHILD SEAT

Potential Number of Units Affected 13,880

#### Summary

Combi USA, Inc. (Combi) is recalling certain Combi BabyRide Infant Car Seats, model 378099 with dates of manufacture of 5/1/2016 thru 8/31/2019. The 1-inch-wide webbing strap used in the center front adjuster to adjust the shoulder harness straps fail the minimum initial breaking strength requirements, and in certain circumstances, may not adequately restrain a child during a crash. As such, these car seats fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) number 213, "Child Restraint Systems."

#### Remedy

The remedy for this recall is still under development. Combi has not yet provided a date for owner notifications. Owners may contact Combi customer service by emailing customerservice@combiusa.com.

#### **Child Seat**

### BRAND MODEL PRODUCTION DATES

COMBI BABYRIDE 05/01/2016 - 08/31/2019