

NHTSA Recalls of Interest September 6, 2021

Seat Belt Automatic Locking Retractor Malfunction

NHTSA Campaign Number: 21V667000

Manufacturer Jaguar Land Rover North America, LLC

Components SEAT BELTS

Potential Number of Units Affected 9,000

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2021-2022 F-Type, 2020-2021 F-Pace, and 2021 XF vehicles. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly.

Remedy

Dealers will inspect and replace the seat belt assemblies as necessary, free of charge. Owner notification letters are expected to be mailed October 22, 2021. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H378.

Vehicles

MAKE MODEL YEAR

JAGUAR F-PACE 2020-2021 JAGUAR F-TYPE 2021-2022 JAGUAR XF 2021

Seat Belt Automatic Locking Retractor Malfunction

NHTSA Campaign Number: 21V668000

Manufacturer Jaguar Land Rover North America, LLC

Components SEAT BELTS

Potential Number of Units Affected 28,000

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2021 Range Rover, 2022 Range Rover Sport, 2020-2021 Range Rover Velar, Discovery Sport, 2020-2022 Discovery, and Defender vehicles. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly.

Remedy

Dealers will inspect and replace the seat belt assemblies as necessary, free of charge. Owner notification letters are expected to be mailed October 22, 2021. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N630.

Vehicles

MAKE	MODEL	YEAR
LAND ROVER D	EFENDER	2020-2022
LAND ROVER D	ISCOVERY	2020-2022
LAND ROVER D	ISCOVERY SPORT	2020-2021
LAND ROVER R	ANGE ROVER	2021
LAND ROVER R	ANGE ROVER SPORT	2022
LAND ROVER R	ANGE ROVER VELAR	2020-2021