



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

October 3, 2022

Blank Instrument Panel Display

NHTSA Campaign Number: 22V710000

Manufacturer General Motors, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 186

Summary

General Motors, LLC (GM) is recalling certain 2023 Cadillac LYRIQ vehicles. A software error in the driver video display control module may cause the instrument panel to go blank.

Remedy

GM will update the video display control module software, free of charge. Owner notification letters are expected to be mailed November 7, 2022. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is N222379510.

Vehicle

MAKE MODEL YEAR

CADILLAC LYRIQ 2023

Rearview Camera May Fail

NHTSA Campaign Number: 22V709000

Manufacturer General Motors, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 95,231

Summary

General Motors, LLC (GM) is recalling certain 2020-2021 Cadillac XT5, XT6, and GMC Acadia vehicles equipped with the optional Surround Vision feature. The rearview camera coaxial cable connectors may have been crimped improperly, causing the rearview camera to fail or function intermittently.

Remedy

Dealers will replace the coaxial cables, free of charge. Letters notifying owners of the safety risk are expected to be mailed November 7, 2022. A second letter will be mailed once the remedy is available. Owners may contact Cadillac customer service at 1-800-458-8006 or GMC customer service at 1-800-462-8782. GM's number for this recall is N222378380.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

CADILLAC	XT5	2020-2021
----------	-----	-----------

CADILLAC	XT6	2020-2021
----------	-----	-----------

GMC	ACADIA	2020-2021
-----	--------	-----------

Brake Lines May Leak

NHTSA Campaign Number: 22V718000

Manufacturer Volkswagen Group of America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 532

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2023 model year Atlas FL and Atlas Cross Sport vehicles. Certain brake lines may leak at the threaded connections.

Remedy

Dealers will replace the affected brake lines, free of charge. Owner notification letters are expected to be mailed on November 23, 2022. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 47T2.

Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	ATLAS	2023
VOLKSWAGEN	ATLAS CROSS SPORT	2023

Tie Rod Clamp Failure

NHTSA Campaign Number: 22V711000

Manufacturer Navistar, Inc.

Components STEERING

Potential Number of Units Affected 451

Summary

Navistar, Inc. (Navistar) is recalling certain 2022-2023 International HX vehicles. The tie rod clamps may have been improperly heat-treated, causing them to fail and allowing the tie rods to separate.

Remedy

Dealers will replace both tie rod end clamps, free of charge. Owner notification letters are expected to be mailed October 3, 2022. Owners may contact Navistar's customer service at 1-800-448-7825. Navistar's number for this recall is 22520.

Vehicle

MAKE	MODEL	YEAR
INTERNATIONAL	HX	2022-2023

Tie Rod Clamps Failure

NHTSA Campaign Number: 22V722000

Manufacturer Daimler Trucks North America, LLC

Components STEERING

Potential Number of Units Affected 36

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2023 Western Star 4700, 4900, 49X, 6900, and Freightliner 114SD vehicles. The tie rod clamps may have been improperly heat-treated, causing them to crack and allowing the tie rods to separate.

Remedy

Dealers will replace the tie rod clamps, free of charge. Owner notification letters are expected to be mailed November 27, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL955.

Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	114SD	2023
WESTERN STAR	4700	2023
WESTERN STAR	4900	2023
WESTERN STAR	49X	2023
WESTERN STAR	6900	2023

Windshield May Detach in a Crash/FMVSS 212

NHTSA Campaign Number: 22V712000

Manufacturer Subaru of America, Inc.

Components VISIBILITY

Potential Number of Units Affected 42

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2022 Impreza and Outback vehicles. The incorrect paint clearcoat may have been applied, which can cause the windshield to be insufficiently bonded to the vehicle. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 212, "Windshield Mounting."

Remedy

Subaru will offer owners a vehicle exchange or repurchase, free of charge. Owner notification letters are expected to be mailed November 21, 2022. Owners may contact Subaru's customer service at 1-844-373-6614. Subaru's number for this recall is WRH-22.

Vehicles

MAKE MODEL YEAR

SUBARU IMPREZA 2022

SUBARU OUTBACK 2022

High Voltage Battery Pack May Short Circuit

NHTSA Campaign Number: 22V705000

Manufacturer Volvo Trucks North America

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 8

Summary

Volvo Trucks North America (Volvo Trucks) is recalling certain 2022-2023 VNRE vehicles. The coolant line in the high voltage battery pack may not be fully seated and locked, which can result in the loss of coolant and an electrical short circuit.

Remedy

Volvo will inspect the battery packs, and replace them as necessary, free of charge. The affected vehicles are within the manufacturer's control and therefore no owner letters will be mailed. Owners may contact Volvo Trucks' customer service at 1-800-528-6586.

Vehicle

MAKE MODEL YEAR

VOLVO VNRE 2022-2023

High Voltage Battery Pack May Short Circuit

NHTSA Campaign Number: 22V706000

Manufacturer Mack Trucks, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 1

Summary

Mack Trucks, Inc. (Mack) is one 2022 truck. The coolant line in the high voltage battery pack may not be fully seated and locked, which can result in the loss of coolant and an electrical short circuit.

Remedy

Mack will inspect the battery packs, and replace them as necessary, free of charge. The affected vehicles are within the manufacturer's control and therefore no owner letters will be mailed. Owners may contact Mack's customer service at 1-800-866-1177.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

MACK	LR ELECTRIC	2022-2023
------	-------------	-----------