



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

January 16, 2023

### Steering Wheel May Lock Up

A screw inside the gearbox housing can cause the steering wheel to lock up and increase the risk of a crash.

**NHTSA Campaign Number:** 23V001000

**Manufacturer** Volvo Car USA, LLC

**Components** STEERING

**Potential Number of Units Affected** 74

#### Summary

Volvo Car USA, LLC (Volvo Car) is recalling certain 2019-2022 V60CC, XC60, and XC90 vehicles. During steering gear assembly, double screws may have been assembled on top of each other, which can cause a screw to fall into the gearbox housing.

#### Remedy

Dealers will replace the steering gear, free of charge. Owner notification letters are expected to be mailed March 1, 2023. Owners may contact Volvo Car's customer service at 1-800-458-1552. Volvo Car's number for this recall is R10213.

#### Vehicles

---

MAKE	MODEL	YEAR
VOLVO	V60CC	2019-2022

---

---

**MAKE****MODEL****YEAR**

VOLVO

XC60

2019-2022

VOLVO

XC90

2019-2022